Oil Field Environmental Incident Summary

Responsible Party: CCS MIDSTREAM SERVICES, LLC **Well Operator:** CCS MIDSTREAM SERVICES, LLC

Well Name: New CCS Waste Oil Treating Plant

Field Name: ALEXANDER Well File #:

 Date Incident:
 4/6/2014
 Time Incident:
 21:30
 Facility ID Number:
 700025-01

 County:
 MCKENZIE
 Twp:
 152
 Rng:
 101
 Sec:
 18
 Qtr:
 SW E2

Location Description: Alexander Treating Plant

Submitted By: Trevor Befus Received By:

Contact Person: Trevor Befus

363 N SAM HOUSTON PKWY E

STE 330

HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Spilled Units Recovered Units Followu
Oil 5 Barrels 5 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Low - all fluid removed from the diking back into tank 3 immediately.

Areal Extent:

Potential Environmental Impacts:

None - all oil was contained in the diking / containment system.

Action Taken or Planned:

Review internal operating procedures and focus on task at hand.

Wastes Disposal Location: Alexander facility

Agencies Involved:

Updates

Date: 5/23/2014 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill happened at a location that does not fall under NDIC jurisdiction. Followup is necessary.

Date: 7/21/2014 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Site was inspected on 4/15/2014 for an incident that occurred the next day involving the same piece of equipment. See spill incident ID 20140407140921 for report.